HLN0509
CA 83

mima
vac

Not USED
Not USED
Not
Not
Not USED
Not USED

This tool was found by the unit after the aircraft returned from Depot maintenance.





An unauthorized and unaccounted for tool left in an aircraft system.